


## TECHNICAL REPORT ARLCB-TR-84022

# **EMBRITTLEMENT OF GUN STEEL BY COPPER**

R.M.FISHER

A. SZIRMAE

M. H. KAMDAR



**JUNE 1984** 



US ARMY ARMAMENT RESEARCH AND DEVELOPMENT CENTER LARGE CALIBER WEAPON SYSTEMS LABORATORY BENÉT WEAPONS LABORATORY WATERVLIET N.Y. 12189

TIE FILE COPY

889

AD-A145

84 08 29 016

#### DISCLAIMER

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

The use of trade name(s) and/or manufacture(s) does not constitute an official indorsement or approval.

## DISPOSITION

Destroy this report when it is no longer needed. Do not return it to the originator.

REPORT DOCUMENTATION	READ INSTRUCTIONS BEFORE COMPLETING FORM	
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
ARLCB-TR-84022	AD-A145889	
4. TITLE (and Subtitle)		5. TYPE OF REPORT & PERIOD COVERED
EMBRITTLEMENT OF GUN STEEL BY COPPER		Final
		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s)		8. CONTRACT OR GRANT NUMBER(s)
R. M. Fisher, A. Szirmae, and M. H. (CONT'D ON REVERSE)	Kamdar	
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
US Army Armament Research & Development Center		AMCMS NO.6111.02.H600.011
Benet Weapons Laboratory, DRSMC-LCB- Watervliet, NY 12189	PRON NO. 1A325B541A1A	
11. CONTROLLING OFFICE NAME AND ADDRESS		12. REPORT DATE
US Army Armament Research & Develop		June 1984
Large Caliber Weapon Systems Laboratory		13. NUMBER OF PAGES
Dover, NJ 07801		19
14. MONITORING AGENCY NAME & ADDRESS(If dilteren	t from Controlling Office)	15. SECURITY CLASS. (of this report)
		UNCLASSIFIED
	•	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)		

#### 16. DISTRIBUTION STATEMENT (of this Report)

Approved for Public Release; Distribution Unlimited

- 17. DISTRIBUTION STATEMENT (of the ebetract entered in Block 20, If different from Report)
- 18. SUPPLEMENTARY NOTES
  Presented at Fall Symposium of AIME, 24-28 October 1982, St. Louis, MO. Published in the Proceedings of Symposium on Liquid and Solid Metal Induced Embrittlement.
- 19. KEY WORDS (Continue on reverse side if necessary and identify by block number)

Embrittlement Gun Steel Copper Rotating Band Liquid Copper Cracking by Copper Rotating Bands

Erosion

20. ABSTRACT (Continue on reverse side if necessary and identify by block number)

Metallographic examination of the bore surfaces of cannon tubes revealed a close association of copper with the erosion and cracking that occurs during firing. Metallic copper, transferred by abrasive contact between the steel surface and the copper rotating band on the projectile that engages the rifling, can induce embrittlement and enhance propagation of cracks developed by the thermal-mechanical stresses generated during firing. Corroborative experiments (CONT'D ON REVERSE)

## 7. AUTHORS (CONT'D)

R. M. Fisher and A. Szirmae U.S. Steel Corporation Research Laboratory Monroeville, PA 15146

## 20. ABSTRACT (CONT'D)

using capacitance discharge heating verified that copper-induced embrittlement and cracking can occur during a thermal pulse of only a few milliseconds duration. Hot tensile testing with a Gleeble machine confirmed that copper penetrates austenite grain boundaries causing hot tearing in just a few seconds at 1000°C, i.e., well below the melting point of copper.

## TABLE OF CONTENTS

	Page
INTRODUCTION	1
METALLOGRAPHIC OBSERVATIONS	3
Fired Cannon Tubes	3
Pulse Heated Specimens	7
Gleeble Hot-Tensile Testing	8
SUMMARY OF EXPERIMENTAL OBSERVATIONS	12
DISCUSSION	14
REFERENCES	16
LIST OF ILLUSTRATIONS	
<ol> <li>Photomicrograph of nickel-plated, polished, and etched cross- section of a fired cannon tube showing white layer and cracks.</li> </ol>	2
<ol> <li>(a). Photomicrograph and x-ray maps of bore surface of fired cannon showing Cu deposition along abrasion marks.</li> </ol>	4
(b). Scanning electron micrograph and x-ray spectra near the abrasion area. The surface is coated with TiO which is added to the propellant.	5
3. Photomicrograph (a) and x-ray map for Cu of fired cannon tube sample fractured under liquid nitrogen to expose surface of longitudinal crack.	6
<ol> <li>Photomicrographs of notched and Cu-plated specimens of gun steel after capacitive-discharge pulse heating to around 1000°C.</li> </ol>	8
<ol> <li>Photomicrographs of a sample of Cu-plated gun steel pulled at 1100°C in a Gleeble hot tensile machine.</li> </ol>	9
6. Scanning electron micrographs of cross-section of 1100°C Gleeble specimen shown in Figure 5. X-ray specimen illustrate the occurrence of Cu at the tip of the rupture.	10

		Page		
7.	Scanning electron micrographs of 1100°C Gleeble specimen and x-ray maps showing high concentration of Cu well ahead of the cracks.			
8.	Scanning electron micrograph of 1100°C Gleeble specimen and computer-processed x-ray map showing presence of Cu in prior austenite grain boundaries.	11		
9.	Photomicrographs (a),(b),(d) of 1050°C Gleeble specimens and scanning electron micrograph (c); (a), (c) = Cu-plated, (b), (c) = not plated.	13		

#### INTRODUCTION

During firing, the bore surfaces of cannon tubes are subjected to very brief (10-20 millisecond duration) but very damaging exposure to high flame temperatures (2-3000°K) and intense thermo-mechanical stresses (50,000 psi) in extremely reactive propellant gases. These conditions cause severe cannon barrel erosion and cracking that has been the subject of extensive and long-standing research at Benet Weapons Laboratory and other laboratories (refs 1-4). Our previous studies (ref 4) were largely concerned with the chemical alterations of the surface stemming from the highly carburizing nature of the spent propellant gases but they also suggested that thermal cracking is aggravated by the effects of Cu-induced embrittlement.

The principal results of the previous investigation are illustrated by the representative optical micrograph of a nickel-plated, polished, and etched cross-section of a fired cannon barrel shown in Figure 1. Four features may be noted: (1) an etch-resistant "white layer" along the surface, (2) regularly spaced shallow cracks in the white layer, (3) occasional very deep cracks penetrating into the steel matrix, (4) a heat-affected zone where very

<sup>&</sup>lt;sup>1</sup>I. Ahmad, "The Problem of Gun Barrel Erosion - An Overview," Proceedings of the Tri-Service Gun Tube Wear and Erosion Symposium, Jean-Paul Picard and Iqbal Ahmad, Eds., ARRADCOM, Dover, NJ, 29-31 March 1977, pp. 1-50.

R. B. Griffin, J. P. Pepe, and C. Morris, "Metallurgical Examination of Bore Surface Damage in a Five-Inch Gun," Metallography, Vol. 8, 1975, pp. 453-471.
 M. H. Kamdar, A. Campbell, and T. Brassard, "A Metallographic Study of White Layer in Gun Steel," ARRADCOM Technical Report No. ARLCB-TR-78012, Benet Weapons Laboratory, Watervliet, NY, August 1978.

<sup>4</sup>R. M. Fisher, A. Szirmae, and M. H. Kamdar, "Metallographic Studies of Erosion and Cracking of Cannon Tubes," Proceedings of the Tri-Service Gun Tube Wear and Erosion Symposium, ARRADCOM, Dover, NJ, 26 October 1982.



50 X

Figure 1. Photomicrograph of nickel-plated, polished, and etched cross-section of a fired cannon tube showing white layer and cracks.

fine carbides have formed. Various analytical and metallographical techniques were used to determine the identity, composition, and structure of phases at and near the surface. It was found that the steel surface is highly carburized to the point of formation of a thin (1-2 um) layer of cementite overlaying a subsurface region (10-20 um) of high carbon austenite (1% C) to comprise the etch-resistant "white layers". Large differential contraction between the surface austenite and the ferrite results in high tensile stresses and cracking of the surface during cooling after the firing cycle. Point to point energy dispersive x-ray analyses (EDXS) during scanning electron microscope (SEM) examination of fired cannon revealed the presence of significant quantities of copper on the bore surface and in the cracks. This discovery prompted a more detailed study of the apparent role of Cu in the

cracking of cannon barrels. In addition to metallographic analysis of fired cannon tubes, a unique apparatus (ref 3) designed and constructed to simulate firing conditions in the laboratory and a Gleeble hot tensile machine were utilized to prepare specimens for the study.

#### METALLOGRAPHIC OBSERVATIONS

#### Fired Cannon Tubes

Visual inspection of the bore surface of fired cannon tubes revealed the occurrence of extended abrasion marks parallel to the rifling as illustrated in Figure 2(a). These abrasion marks which are not readily discernible because of wear of the cannon tube, are spaced about 1 cm apart which corresponds to the separation of the rectangular corrugations on the Cu rotating band on the projectile which engages the rifling on the bore to impose a twisting movement to the projectile. It may also be noted on the figure that the longitudinal cracks are also parallel to abrasion marks and not the bore axis. A SEM image of the bore surface of this sample is shown in Figure 2(b) illustrating the corn-cob-like structure of the heat check pattern and an example of a deeply penetrating longitudinal crack. The EDXS spectrum from this area included in the figure shows the presence of Al, S, K, Ti, and Cu in addition to Fe from the steel base. Point to point EDXS analysis showed that the surface is coated with Ti and the other elements present in the propellant except at some region in the center of the figure where they were

<sup>&</sup>lt;sup>3</sup>M. H. Kamdar, A. Campbell, and T. Brassard, "A Metallographic Study of White Layer in Gun Steel," ARRADCOM Technical Report No. ARLCB-TR-78012, Benet Weapons Laboratory, Watervliet, NY, August 1978.

removed by contact by the rapidly moving rotating band. In this region the steel base was exposed by abrasion and Cu deposited as illustrated by the x-ray maps for Ti, K, Fe, and Cu of the lower left-hand region of Figure 2.




Figure 2(a). Photomicrograph and x-ray maps of bore surface of fired cannon showing Cu deposition along abrasion marks.




Figure 2(b). Scanning electron micrograph and x-ray spectra no the abrasion area. The surface is coated with TiO which is maded to the propellant.

A striking demonstration of the penetration of Cu into the deep cracks is illustrated in Figure 3. The micrograph in Figure 3(a) shows the bore surface of a fired cannon tube. The sample was mounted in a small clamp with the crack parallel to the jaws, chilled in liquid N2, and then fractured to expose the pre-existing crack surfaces. (The broken halves were reassembled for the micrograph in Figure 3(a).) One of the fracture surfaces and the corresponding x-ray map for Cu are shown in Figure 3(b). Penetration of Cu to the tip of the 0.4 mm deep crack is quite evident.




Figure 3. Photomicrograph (a) and x-ray map for Cu of fired cannon tube sample fractured under liquid nitrogen to expose surface of longitudinal crack.

#### Pulse Heated Specimens

A special pulse heating apparatus has been assembled at Benet Weapons
Laboratory (ref 3) and used to successfully simulate the rapid heating and
cooling gun steel (ASTM-A273 Grade 3), and the formation of white layer that
occurs in several milliseconds during firing of a large cannon. The apparatus
consists of a variable time-delay system for firing a parallel array of
capacitors to make it possible to simulate a wide range of heating cycles in a
high pressure atmosphere of methane or other gases if desired. This same
apparatus was used to determine if the embrittling effects of Cu can occur
during the short exposure intervals that occur during very rapid heating.

A low magnification photomicrograph of a notched and Cu-plated specimen after pulse heating near the melting point of copper is shown in Figure 4. Although the specimen was not heated to the melting point of copper, the "heat-affected" zone is clearly evident due to recyrstallization of the copper plating. After polishing, a crack can be seen emanating from the root of the notch as shown in Figure 4(b) and after etching (Figure 4(c)). Faint traces of Cu were detected along the crack by EDXS. The effects were much more pronounced when specimens were heated above the melting point of copper but no cracking occurred with samples that were not Cu-plated.

<sup>&</sup>lt;sup>3</sup>M. H. Kamdar, A. Campbell, and T. Brassard, "A Metallographic Study of White Layer in Gun Steel," ARRADCOM Technical Report No. ARLCB-TR-78012, Benet Weapons Laboratory, Watervliet, NY, August 1978.




Figure 4. Photomicrographs of notched and Cu-plated specimens of gun steel after capacitive-discharge pulse heating to around 1000°C.

## Gleeble Hot-Tensile Testing

Direct evidence for the embrittlement of gun steel by copper was also obtained using a Gleeble Model 1500 hot-tensile testing machine. Specimens, one-half inch in diameter, were machined from gun steel and Cu-plated over the reduced cross-section using masking tape. Specimens were pulled at nominal center temperatures of 1000, 1050, and  $1100^{\circ}$ C at various strain rates around  $10^{-1}$  to  $-10^{-1}$  per minute. In a few cases, attempts to stop the tests prior to complete rupture were successful.

Macrophotographs of a Cu-plated sample pulled at 1100°C at a strain rate of 10<sup>1</sup>/min. are shown in Figure 5. The occurrence of classical hot-tearing due to an embrittling agent is quite evident. No indication of hot-tearing was found on specimens that were not Cu-plated but were tested under similar conditions. The depth of penetration of the hot-tears varied considerably. Scanning electron micrographs of a longitudinal section of the 1100°C Gleeble specimen are shown in Figure 6. X-ray spectrochemical analysis in the SEM confirmed the presence of Cu at the tip of the cracks as is demonstrated by the inset on the figure.




Figure 5. Photomicrographs of a sample of Cu-plated gun steel pulled at 1100°C in a Gleeble hot tensile machine.




Figure 6. Scanning electron micrographs of cross-section of 1100°C Gleeble specimen shown in Figure 5. X-ray specimen illustrates the occurrence of Cu at the tip of the rupture.

Metallographical examination of areas between the deep fissures shown in the macrograph provided information about the distribution of Cu ahead of the ruptures. A good example is illustrated by the SEM and Cu x-ray maps in Figure 7 which shows a high concentration of Cu in a prior austenite grain boundary. Another example of grain boundary Cu is shown at higher magnification in Figure 8. Computer-processing of the x-ray signal to improve contrast and definition serves to enhance the image of the Cu concentration as shown in the x-ray map of Figure 8(b).




Figure 7. Scanning electron micrograph of 1100°C Gleeble specimen and x-ray maps showing high concentration of Cu well ahead of the cracks.




Figure 8. (a) Scanning electron micrograph of 1100°C Gleeble specimen, and (b) computer-processed x-ray map showing presence of Cu in prior austenite grain boundaries.

The effect of temperature on Cu embrittlement during Gleeble hot-tensile testing was investigated by running a few specimens at 1000°C and 1050°C. Examples of samples of gun steel strained at 1050°C with and without Cu-plating are shown in Figure 9. (The temperature, which refers to the reading of the thermocouple attached to the center of the gauge length, is lower at the limits of the reduced cross-section.) It is very clear that the effect of Cu on hot-tearing is very pronounced even below its melting point. Generally, similar results were obtained at 1000°C. The scanning electron micrograph (Figure 9(c)) illustrates the highly strained structure that develops near the the apex of the fracture core. In the case of the Cu-plated sample, decohesion of the grain boundaries occurs so that the individual grains, or small clusters, remain in place - largely undeformed, while the interior region - unaffected by copper, deforms plastically. In the absence of Cu, the surface and interior grains deform homogeneously. This effect is very similar to the separation of polycrystalline aluminum into individual grains using gallium that is described by Rhines and Gokhale (ref 5).

#### SUMMARY OF EXPERIMENTAL OBSERVATIONS

The relevant experimental findings are as follows: (1) Copper is transferred by abrasion from the Cu rotating band on the projectile to the surface of the cannon tube. (2) The copper penetrates heat-check cracks that

<sup>&</sup>lt;sup>5</sup>F. N. Rhines and A. B. Gokhale, "Measurement of Topology and Size Distribution of Grains in Aluminum by Penetration With Liquid Gallium," Liquid and Solid Metal Embrittlement, M. H. Kamdar, Ed., AIME, June 1984.




Figure 9. Photomicrographs (a,b,d) of 1050°C Gleeble specimens and scanning electron micrograph (c); a,c = Cu-plated, b,c = not plated.

are caused by rapid heating and cooling during and after firing. (3) The growth of some of the heat-check cracks into deep penetrating fatigue cracks is enhanced by Cu-embrittlement. (4) Cu-embrittlement can occur during heat pulses of only a few milliseconds duration. (5) Cu-embrittlement can occur at temperatures of 1000°C or less, i.e., well below the melting point of Cu. (6) Cu penetrates prior austenite grain boundaries well ahead of surface cracks.

#### DISCUSSION

The metallographic studies of both fired cannon samples and specimens pulse heated or rapidly strained in the laboratory show direct correlation between the presence of copper and cracking of the surface. Both of these situations are very different from the usual occurrence of hot-shortness due to copper (ref 6). In hot-shortness, the copper segregation is the result of preferential scaling of the steel resulting in a buildup of copper at the interface until it exceeds the solubility of austenite and forms metallic copper. Above its melting point, the copper can weaken the grain boundaries and cause rupture of the surface in the presence of tensile stresses during rolling or other mechanical working processes. Another major difference with hot-shortness due to copper that may occur during hot-rolling of steel is that the surface will be above the melting point of copper for just a few milliseconds. Despite the very brief duration of the exposure to liquid

<sup>6</sup>D. A. Melford, "The Influence of Residual and Trace Elements on Hot-Shortness and High Temperature Embrittlement," Phil. Trans. R. Soc., London, A295, 1980, pp. 89-103.

copper and the very steep temperature gradient below the surface, copper is present right to the tips of the cracks.

In summary, the embrittling effects of copper, commonly associated with hot-working processes are also evident when metallic copper is in contact with steel at high temperatures and in the presence of tensile stresses. In some cases, the embrittlement is due to classical reduction in cohesion at the grain boundary by the presence of liquid copper. However, penetration of copper along grain boundaries (ref 7) below its melting point can also result in reduction in the grain boundary cohesion (refs 8-10) and rupture. Constant temperature and fixed load testing are required to establish the minimum temperature for solid metal embrittlement by copper. Cracks initiated by Cu liquid-solid metal embrittlement may continue to propagate during cooling under the influence of thermally-induced stresses.

<sup>7</sup>G. R. Speich, J. A. Gula, and R. M. Fisher, "Diffusivity and Solubility Limit of Copper in Alpha and Gamma Iron," in The Electron Microprobe, T. D. McKinley, K. F. J. Heinrich, and D. B. Witty, Eds., Symposium of the Electrochemical Society, Washington, D.C., October 1974, pp. 525-542.

8N. S. Stoloff, "Metal Induced Embrittlement - A Historical Perspective," Liquid and Solid Metal Embrittlement, M. H. Kamdar, Ed., AIME, June 1984.

9M. H. Kamdar, "Liquid Metal Embrittlement," Embrittlement of Engineering Alloys, C. L. Briant and S. F. Banarji, Eds., Academic Press, New York, 1983.

<sup>10</sup>C. L. Briant and R. P. Messmer, "Chemical Bonding and Grain Boundary Embrittlement," <u>Liquid and Solid Metal Embrittlement</u>, M. H. Kamdar, Ed., AIME, June 1984.

#### REFERENCES

- 1. I. Ahmad, "The Problem of Gun Barrel Erosion An Overview," Proceedings of the Tri-Service Gun Tube Wear and Erosion Symposium, Jean-Paul Picard and Iqbal Ahmad, Eds., ARRADCOM, Dover, NJ, 29-31 March 1977, pp. 1-50.
- R. B. Griffin, J. P. Pepe, and C. Morris, "Metallurgical Examination of Bore Surface Damage in a Five-Inch Gun," <u>Metallography</u>, Vol. 8, 1975, pp. 453-471.
- M. H. Kamdar, A. Campbell, and T. Brassard, "A Metallographic Study of White Layer in Gun Steel," ARRADCOM Technical Report No. ARLCB-TR-78012, Benet Weapons Laboratory, Watervliet, NY, August 1978.
- 4. R. M. Fisher, A. Szirmae, and M. H. Kamdar, "Metallographic Studies of Erosion and Cracking of Cannon Tubes," Proceedings of the Tri-Service Gun Tube Wear and Erosion Symposium, ARRADCOM, Dover, NJ, 26 October 1982.
- 5. F. N. Rhines and A. B. Gokhale, "Measurement of Topology and Size Distribution of Grains in Aluminum by Penetration With Liquid Gallium," Liquid and Solid Metal Embrittlement, M. H. Kamdar, Ed., AIME, June 1984.
- 6. D. A. Melford, "The Influence of Residual and Trace Elements on Hot-Shortness and High Temperature Embrittlement," Phil. Trans. R. Soc., London, A295, 1980, pp. 89-103.
- 7. G. R. Speich, J. A. Gula, and R. M. Fisher, "Diffusivity and Solubility Limit of Copper in Alpha and Gamma Iron," in <u>The Electron Microprobe</u>, T. D. McKinley, K. F. J. Heinrich, and D. B. Witty, Eds., Symposium of the Electrochemical Society, Washington, D.C., October 1974, pp. 525-542.

- 8. N. S. Stoloff, "Metal Induced Embrittlement A Historical Perspective,"

  Liquid and Solid Metal Embrittlement, M. H. Kamdar, Ed., AIME, June 1984.
- 9. M. H. Kamdar, "Liquid Metal Embrittlement," Embrittlement of Engineering

  Alloys, C. L. Briant and S. F. Banarji, Eds., Academic Press, New York,

  1983.
- 10. C. L. Briant and R. P. Messmer, "Chemical Bonding and Grain Boundary

  Embrittlement," Liquid and Solid Metal Embrittlement, M. H. Kamdar, Ed.,

  AIME, June 1984.

#### TECHNICAL REPORT INTERNAL DISTRIBUTION LIST

	NO. OF COPIES
CHIEF, DEVELOPMENT ENGINEERING BRANCH	
ATTN: DRSMC-LCB-D	1
-DP	1
-DR	1
-DS (SYSTEMS)	1
-DS (ICAS GROUP)	1
-DC	1
CHIEF, ENGINEERING SUPPORT BRANCH	
ATTN: DRSMC-LCB-S	1
-SE	1
CHIEF, RESEARCH BRANCH	
ATTN: DRSMC-LCB-R	2
-R (ELLEN FOGARTY)	1
-RA	1
-RM	2
-RP	1
-RT	1
TECHNICAL LIBRARY ATTN: DRSMC-LCB-TL	5
TECHNICAL PUBLICATIONS & EDITING UNIT ATTN: DRSMC-LCB-TL	2
DIRECTOR, OPERATIONS DIRECTORATE	1
DIRECTOR, PROCUREMENT DIRECTORATE	1
DIRECTOR, PRODUCT ASSURANCE DIRECTORATE	ı

NOTE: PLEASE NOTIFY DIRECTOR, BENET WEAPONS LABORATORY, ATTN: DRSMC-LCB-TL, OF ANY ADDRESS CHANGES.

## TECHNICAL REPORT EXTERNAL DISTRIBUTION LIST

	NO. OF COPIES		NO. OF COPIES
ASST SEC OF THE ARMY RESEARCH & DEVELOPMENT ATTN: DEP FOR SCI & TECH THE PENTAGON WASHINGTON, D.C. 20315	1	COMMANDER US ARMY AMCCOM ATTN: DRSMC-LEP-L(R) ROCK ISLAND, IL 61299	1
COMMANDER DEFENSE TECHNICAL INFO CENTER ATTN: DTIC-DDA CAMERON STATION	12	COMMANDER ROCK ISLAND ARSENAL ATTN: SMCRI-ENM (MAT SCI DIV) ROCK ISLAND, IL 61299	1
COMMANDER US ARMY MAT DEV & READ COMD	1	DIRECTOR US ARMY INDUSTRIAL BASE ENG ACTV ATTN: DRXIB-M ROCK ISLAND, IL 61299	1
ATTN: DRCDE-SG 5001 EISENHOWER AVE ALEXANDRIA, VA 22333	1	COMMANDER US ARMY TANK-AUTMV R&D COMD ATTN: TECH LIB - DRSTA-TSL	1
COMMANDER ARMAMENT RES & DEV CTR US ARMY AMCCOM ATTN: DRSMC-LC(D)	1 1	COMMANDER US ARMY TANK-AUTMV COMD ATTN: DRSTA-RC	1
DRSMC-LCE(D) DRSMC-LCM(D) (BLDG 321) DRSMC-LCS(D) DRSMC-LCU(D)	1 1 1 1	WARREN, MI 48090 COMMANDER	
DRSMC-LCW(D) DRSMC-SCM-O (PLASTICS TECH EVAL CTR, BLDG. 351N)	ī	US MILITARY ACADEMY ATTN: CHMN, MECH ENGR DEPT WEST POINT, NY 10996	1
DRSMC-TSS(D) (STINFO) DOVER, NJ 07801 DIRECTOR	2	US ARMY MISSILE COMD REDSTONE SCIENTIFIC INFO CTR ATTN: DOCUMENTS SECT, BLDG. 448 REDSTONE ARSENAL, AL 35898	2
BALLISTICS RESEARCH LABORATORY ARMAMENT RESEARCH & DEV CTR US ARMY AMCCOM ATTN: DRSMC-TSB-S (STINFO) ABERDEEN PROVING GROUND, MD 21005	1	COMMANDER US ARMY FGN SCIENCE & TECH CTR ATTN: DRXST-SD 220 7TH STREET, N.E. CHARLOTTESVILLE, VA 22901	1
MATERIEL SYSTEMS ANALYSIS ACTV ATTN: DRSXY-MP ABERDEEN PROVING GROUND, MD 21005	1	OHRHAVITADVIBBIS, VA 22701	

NOTE: PLEASE NOTIFY COMMANDER, ARMAMENT RESEARCH AND DEVELOPMENT CENTER, US ARMY AMCCOM, ATTN: BENET WEAPONS LABORATORY, DRSMC-LCB-TL, WATERVLIET, NY 12189, OF ANY ADDRESS CHANGES.

#### TECHNICAL REPORT EXTERNAL DISTRIBUTION LIST (CONT'D)

	NO. OF		NO. ОР
	COPIES		COPIES
COMMANDER US ARMY MATERIALS & MECHANICS RESEARCH CENTER ATTN: TECH LIB - DRXMR-PL WATERTOWN, MA 01272	2	DIRECTOR US NAVAL RESEARCH LAB ATTN: DIR, MECH DIV CODE 26-27, (DOC LIB) WASHINGTON, D.C. 20375	1
COMMANDER US ARMY RESEARCH OFFICE ATTN: CHIEF, IPO P.O. BOX 12211 RESEARCH TRIANGLE PARK, NC 27709	I	COMMANDER AIR FORCE ARMAMENT LABORATORY ATTN: AFAIL/DLJ AFAIL/DLJC EGLIN AFB, FL 32542	1
COMMANDER US ARMY HARRY DIAMOND LAB ATTN: TECH LIB 2800 POWDER MILL ROAD ADELPHIA, MD 20783	I	METALS & CERAMICS INFO CIR BATTELLE COLUMBUS LAB 505 KING AVENUE COLUMBUS, OH 43201	1
COMMANDER NAVAL SURFACE WEAPONS CTR ATTN: TECHNICAL LIBRARY CODE X212 DAHLGREN, VA 22448	ı		

NOTE: PLEASE NOTIFY COMMANDER, ARMAMENT RESEARCH AND DEVELOPMENT CENTER, US ARMY AMCCOM, ATTN: BENET WEAPONS LABORATORY, DRSMC-LCB-TL, WATERVLIET, NY 12189, OF ANY ADDRESS CHANGES.